


**100% Inspection
COVERAGE**

DEMO REPORT





100% inspection COVERAGE DEMO REPORT

Date: May 25, 2022.




Location: Demo Farm, 43.3603244, 16.2910421

Cage: ATEU1HRV0531



Percentage of covered cage/net area

78%

-  Uncovered cage/net area
-  Covered with ROV inspection
-  Useable frames from video



KARMENstudio
advanced aquaculture video analysis

